



June 2002

All Authorised Examiners and Designated Councils in Classes I and II.

The last Special Notice was: 2/2002 All Classes

### CONTENTS OF SPECIAL NOTICE

Item	Page	Subject	Relevant to
1	1	Inspection Manual Temporary Pages	AEs and Testers
2	2	Consolidated Special Notice (issue 3)	AEs and Testers

#### Item 1 Inspection Manual Temporary Pages

The temporary pages enclosed with this Special Notice are being issued for the following reasons.

- The Inspection Manual will soon be revised to consist of seven sections. This will align to the forthcoming revised Class III, IV and VII Inspection manual.
- Following feedback from the trade some Methods of Inspection (MoI) and Reasons for Rejection (RfR) have been more fully described and made easier to understand.
- Appendix C is now included in the MOT Testing Guide.
- It is our intention to remove all items in the MoI and RfR columns that make reference to the information column as pages are amended. The temporary pages attached have had these references removed as will any pages subsequently issued. This is because the information column should always be referred to before any decision is made. References to individual items were therefore felt to be unnecessary.

Please insert the pages (detailed below) into your Inspection Manual on receipt of this Special Notice. Permanent pages will be issued at a later date.

All Nominated Testers should sign below to confirm that they have read and understood the contents of this Special Notice relevant to NTs for the classes they test. AEs must keep a copy of the signed SN on their records.


To help preserve the temporary pages you may wish to:

- glue, staple or similar to the existing page as indicated by “Cover”.
- laminate or place new pages, indicated by “Add”, in a plastic sleeve prior to insertion into the manual.

Cover the existing Manual Contents page with temporary Manual Contents

Cover the existing Section 1 contents page with temporary Section 1 contents page

Cover the existing 1.5 Direction Indicators, page 8, with the temporary 1.5 page 8.

Add 1.7 Horn (Audible Warning) temporary page to the back of Section 1.

Cover the existing 2.1 Steering Controls, page 3, with temporary 2.1 page 3.

Cover the existing 2.5 Wheel Alignment (Solo Machine), page 10, with temporary 2.5 page 10.

Cover the existing 3.1 Brake Controls, page 2, with temporary 3.1 page 2.

Cover the existing 3.2 Brake Systems, page 7, with temporary 3.2 page 7.

Remove the existing Section 6 completely.

Add new divider - Section 6 Structure

Add the temporary Section 6 Contents

Add the temporary 6.1 Condition of Structure, page 2.

Add the temporary 6.2 Seats, footrests and transmission, page 3.

Add new divider - Section 7 Exhaust

Add the temporary Section 7 Contents page

Add the temporary 7.1 Exhaust System

Remove Appendix C

---

### **Item 2 Consolidated Special Notice Issue 3**

Following the updating of the MOT Testing Guide the Special Notices have been reviewed. Please keep the attached Consolidated Special Notice (issue 3) and Special Notices 7/2001 and 2/2002 onward.

All other Class I and II Special Notices, including the previous Consolidated SN Issue 2, should be destroyed.

Alan Wilson  
Head of MOT Scheme Management