



# Vehicle Inspectorate

**MOT  
SPECIAL  
NOTICE  
7/2002**

July 2002

All Authorised Examiners and Designated Councils in All Classes

The last Special Notice was: 5/2002 Class V  
6/2002 Class IV and VII

---

## CONTENTS OF SPECIAL NOTICE

Item	Page	Subject	Relevant to
1	1	<b>MOT testing fees from 1 August 2002</b>	AEs
2	2	<b>Data cleansing</b>	AEs
3	2	<b>Embossing VT30</b>	AEs and NTs

### **Item 1 MOT testing fees from 1 August 2002.**

The MOT Test fee maximum has been changed. You may charge increased MOT fees on and after 1 August 2002

Enclosed with this Special Notice is the new fees poster that you must display on your MOT notice board after 31 July 2002. Please ensure that you add your Local Area Office address to it

The price of a pad of VT20 test certificates will remain the same.

This Special Notice updates the fees set out in the MOT Guide Section L Page1

---

**All Nominated Testers should sign below to confirm that they have read and understood the contents of this Special Notice relevant to NTs for the classes they test. AEs must keep a copy of the signed SN on their records.**


The revised fees will be	
Class I and II	
Motor bicycles	£14.65
Motor bicycle with side car	£24.05
Class III	£28.15
Class IV	£39.25
Private Passenger Vehicles and ambulances	£41.10
Class IVA	£46.20
Class V	
13-16 passenger seats	£44.45
More than 16 passenger seats	£60.35
Class VA	
13-16 passenger seats	£60.20
more than 16 passenger seats	£93.30
Class VII	
Goods vehicles over 3000kg up to 3500Kg DGW	£43.15

---

## **Item 2 Data cleansing**

The data cleansing forms you completed recently should have ensured that the details of all Authorised Examiners, Vehicle Testing Stations and Nominated Testers are correct ready for the roll out of Computerisation.

It is important that the data remains correct and up to date.

The MOT Guide Section B3 sets out the changes to authorisations we need to be told about. It is also important that the testers are correctly listed.

If you make changes to your business or you notice that your address, authorisation or tester details appear to be incorrect please contact your Local VI office.

---

## **Item 3 Embossing VT30**

The Guide example shows an embossed carbon. The original VT30 must be embossed. There is no requirement to emboss the carbon copy.

Alan Wilson  
Head of MOT Scheme Management